

Advanced Aircraft Center Inc

14299 SW 127th St, Suite 101

Miami, Florida 33186

Ph: 305-259-8291 Fx: 305-259-8302

www.advancedaircraftcenter.com

Shop Order: 26-8009

Opened: 3/30/2026
Close Date:

Sold To: Cirrus

Aircraft Number:	N725CP	Type:	Cirrus SR22	S/N:	3352		
Eng#	Type	S/N	Time	Cycles	Prop Type	Prop S/N	Prop Time

Discrepancy: 1

Problem:

Overhaul Engine Quote + Labor

Instructions:

DOES NOT INCLUDE TEST FLIGHT AND FUEL

THERE IS A \$25,000 CORE CHARGE THAT WILL BE ADDED TO YOUR BILL IF YOUR ENGINE DOES NOT PASS A NORMAL RUN OUT OUT ENGINE CORE. COMPLETE WITH ALL ACCESSORIE. THE ENGINE CRANKSHAFT, CRANKCASE, INTERNAL STEEL, CONNECTING RODS, AND ALL INTERNAL GEARS INSPECTION, WHEN WE SEND YOUR ENGINE IN FOR A CORE.

	Projected	Billed	Charges
Charges This Item:	0.00	70.00 Hours @ 195.00	\$ 13,650.00
		Outside Parts - Gaskets And Hardware:	\$ 400.00
		Inbound Freight:	\$ 400.00
		Outbound Freight:	\$ 400.00
		Miscellaneous - BA24 Filter:	\$ 24.00
		Miscellaneous - Oil & Filter:	\$ 225.00
		Miscellaneous - Overhaul IO550N Engine:	\$ 75,600.00
		Total For This Discrepancy:	\$ 90,699.00

Discrepancy: 2

Problem:

Propeller Overhaul + Labor

Instructions:

	Projected	Billed	Charges
Charges This Item:	0.00	2.00 Hours @ 195.00	\$ 390.00
		Inbound Freight:	\$ 150.00
		Outbound Freight:	\$ 150.00
		Miscellaneous - Propeller Overhaul:	\$ 10,995.00
		Total For This Discrepancy:	\$ 11,685.00

Discrepancy: 3

Advanced Aircraft Center Inc

14299 SW 127th St, Suite 101

Miami, Florida 33186

Ph: 305-259-8291 Fx: 305-259-8302

www.advancedaircraftcenter.com

Problem:

Governor Overhaul + Labor

Instructions:

Charges This Item:

Projected	Billed	Charges
0.00	1.00 Hours @ 195.00	\$ 195.00
	Inbound Freight:	\$ 45.00
	Outbound Freight:	\$ 45.00
	Miscellaneous - Governor Overhaul:	\$ 2,695.00
	Total For This Discrepancy:	\$ 2,980.00

Discrepancy: 4

Problem:

Engine Isolators

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
	Total For This Discrepancy:	\$ 0.00

Discrepancy: 5

Problem:

Engine Hoses And Fuel Hoses

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
	Total For This Discrepancy:	\$ 0.00

Discrepancy: 6

Problem:

Exhaust System

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
	Total For This Discrepancy:	\$ 0.00

Discrepancy: 7

Problem:

Engine Baffles

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
	Total For This Discrepancy:	\$ 0.00

Discrepancy: 8

Problem:

Electric Boost Pump

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
	Total For This Discrepancy:	\$ 0.00

Discrepancy: 9

Problem:

Advanced Aircraft Center Inc

14299 SW 127th St, Suite 101

Miami, Florida 33186

Ph: 305-259-8291 Fx: 305-259-8302

www.advancedaircraftcenter.com

Manifold Pressure Sensor, Oil Pressure Sensor, Oil Temperature Sensor, CHT Sensors, EGT Sensors

Instructions:

WILL ADVISE UPON INSPECTION OF ENGINE REMOVAL

Projected	Billed	Charges
		0.00
Total For This Discrepancy:		\$

Discrepancy: 10

Problem:

Cirrus Line Cutters

Instructions:

Projected	Billed	Charges
		2,200.00
Outside Parts:		\$
Total For This Discrepancy:		\$

Charges This Item:

Discrepancy: 11

Problem:

Cirrus Parachute And Rocket ASSY

Instructions:

Projected	Billed	Charges
		22,000.00
Outside Parts:		\$
Total For This Discrepancy:		\$

Charges This Item:

Miscellaneous Charges:

Shop Supplies:	\$	1,823.52
----------------	----	----------

Summary:

Total Freight:	\$	1,190.00	Shop Supplies:	\$	1,823.52
Total Labor - 73.00 Hours:	\$	14,235.00	Projected Labor - 0.00 Hours:	\$	
Total Outside Parts:	\$	24,600.00	Miscellaneous:	\$	89,539.00

Totals:

SubTotal:	\$	131,387.52
Total Charges:	\$	131,387.52
Amount Remaining:	\$	131,387.52